




SUMMARY

UPS FOR THE INTERNET • MODEM • ROUTER • ONT



- 1 WATT METER • PRESS WATT
- 2 ADD THE WATTS
- 3 UPS IN W • UNDER 80 %
- 4 RUNTIME CHART AT YOUR W
- 5 BATTERY OUTLETS
- 6 PULL THE PLUG • TIME IT

BE600M1: 33 W 1 h 22 min • 50 W 52 min • 100 W 23 min

Short? Charge 10 h, test again.

Gear drops? Add back one at a time.

Still failing? Charge 24 h, then new battery.

integratornotes.com/cards/027

INTEGRATOR NOTES

@integratornotes